





TS 5000
TS 5000 S
TS 5000 SoftClose

107934-05




GEZE




5 mm

A















$a \leq 1400 \text{ mm}$


B




$a \leq 1400 \text{ mm}$




1




2




3




4



5





6



7





5 mm








a (mm) – EN



1400 - 6.







8







TS 5000 S



i+ TS 5000 SoftClose



9

 $a \leq 1400 \text{ mm}$  $a \leq 1400 \text{ mm}$ 